Release Date: June 30, 2014

#### **VRMF Level Data Results:**

VRMF level From:	76.31.92.0
VRMF Level To:	76.31.105.0
Report for:	All DS8700

## **Code Bundle Contents**

This table includes code component reference information.

DS8000 Code Bundle Level	SEA or LMC Version: Used with dscli <i>ver</i> command.		Storage Manager Code Level
76.31.105.0	6.6.31.1000	6.6.31.1000	5.6.31.1230

Overview of new features and functions supported by this release on DS8700, 242x model 941

## At a glance:

- Apache Struts v1 vulnerability fix
- Problem fixes
- Serviceability enhancements
- Improvements

## This new microcode release only supports the DS8800.

#### **Select Modifications Included in this Release Note:**

This is a list of some modifications contained across one or more LIC (License Internal Code) or microcode release(s). The potential impact is variable. Specific environments may aggravate or degrade the potential impact. Problem(s) fixed and reported in this release note may not be in higher levels of code bundles.

#### **Definition of Problem Severity:**

1 High Impact - Acute: An irrecoverable error with potential loss of data.

- Serious: An irrecoverable error with potential loss of access to data.

2 Moderate - A function not operational and/or performance might be degraded.

3 Service - A recoverable error (no impact) and service improvements.

4 Improvements - Improvement changes for better Usability and Serviceability.

HIPER: High Impact problem that is Pervasive: 3 or more occurrences

Acute: An irrecoverable error with potential loss of data.

None

## Serious: An irrecoverable error with potential loss of access to data.

## **Loss of access during Smart Rebuild**

- **1. Problem Description:** Smart rebuild abort because of errors on source drive caused Device Adapter showstop errors
- 2. Potential Impact of Problem: loss of access
- 3. Problem Severity: HIPER4. Pervasive Problem: Yes

ID#: 266319

## I/O timeout caused by Smart Rebuild source drive failure

- **1. Problem Description:** During Smart Rebuild, source drive failed, and disappeared from the loop, causing array offline for ~90 seconds
- 2. Potential Impact of Problem: I/O timeout, loss of access
- Problem Severity: HIPER
  Pervasive Problem: Yes

ID#: 283070

#### Internal communication error causes enclosure power off

- 1. **Problem Description:** Communication failure between the enclosure controller cards can result in both cards taking control of the internal serial bus which can result in the storage enclosure powering off.
- 2. Potential Impact of Problem: loss of access
- Problem Severity: HIPER
  Pervasive Problem: Yes

ID#: 292022

### Track Space Efficient repository greater than 19GB exposure

- 1. **Problem Description:** Track Space Efficient (TSE) repositories greater than 19TB (19456 GB) are exposed to corruption of the data contained in the repository that can result in a loss of access.
- 2. Potential Impact of Problem: loss of access
- 3. Problem Severity: High Impact
- 4. Pervasive Problem: No

ID#: 293344

## Multiple 0x0632 MLE when set or reset soft fence

- 1. **Problem Description:** Command chain containing 0x2A order to set/ reset soft fence is prohibited, triggering a warmstart. The warmstart then returns redrive sense to the host.
- 2. Potential Impact of Problem: loss of access
- 3. Problem Severity: High Impact
- 4. Pervasive Problem: No

## **Dual host bay PCIe recovery**

1. **Problem Description:** During PCIe error recovery, arrays attempt to fail over to the alternate adapter, but a latent fabric error in the alternate host bay triggered PCIe error recovery in that bay as well.

2. Potential Impact of Problem: loss of access

3. Problem Severity: High Impact

4. Pervasive Problem: No

ID#: 294812

# Moderate: A system path is not operational and performance may be degraded.

## LUNs in hybrid pools reported as SSD

**1. Problem Description:** LUNs in hybrid pools consisting of both solid-state and rotational drives are all being reported as SSD.

2. Potential Impact of Problem: degraded performance

Problem Severity: Moderate
 Pervasive Problem: No

ID#: 295996

### Global Mirror drain failure recovery

1. **Problem Description:** When the Global Copy Collision code is enabled, if a Global Mirror collision occurs together with a Global Copy collision, the Global Mirror collision may be queued behind the Global Copy transfer.

2. Potential Impact of Problem: Elongated consistency group times

3. Problem Severity: Moderate4. Pervasive Problem: No

ID#: 296338

## Service: A recoverable error, Service improvements.

## Failed USB ethernet adapter detection

**1.Problem Description:** If one USB ethernet adapter is failing during an HMC reboot, the problem does not generate a serviceable event until healthcheck discovers the problem. This change will generate a serviceable event for the failed adapter once the reboot completes.

2. Potential Impact of Problem: Additional service call

3.Problem Severity: Service4.Pervasive Problem: No

ID#: 280696

#### **SRVE0232E Internal Server Error**

1. **Problem Description:** DS GUI fails login with SRVE0232E because of an out-of-memory condition

2. Potential Impact of Problem: Unable to login to HMC

Problem Severity: Service
 Pervasive Problem: No

## **RAS FRU isolation improvement for loop errors**

1. **Problem Description:** Corrects an issue where a DDM was rejected, and the loop errors caused by that DDM were incorrectly attributed to the device adapter

2. Potential Impact of Problem: none

3. Problem Severity: Service 4. Pervasive Problem: No.

ID#: 286661

#### **Improved handling of Lost Data Frame errors**

- 1. Problem Description: When a serviceable event is generated for Lost Data Frame errors on a Device Adapter loop, the affected loop will be placed in service mode.
- 2. Potential Impact of Problem: none
- 3. Problem Severity: Service 4. Pervasive Problem: No

ID#: 289221

## 0x1638 MLE updating erProduct switch

- 1. Problem Description: While device adapter was updating erProduct switch flag, the operation was swapped out, then resumed on a different processor, resulting in a locking exception.
- 2. Potential Impact of Problem: Warmstart
- 3. Problem Severity: Service 4. Pervasive Problem: No

ID#: 291258

## **Secure Data Overwrite failure on CEC hard drives**

- 1. **Problem Description:** One CEC completes the SDO process ahead of the other, and attempts to resume before the other completes the mirroring process
- 2. Potential Impact of Problem: SDO does not complete
- 3. Problem Severity: Service 4. Pervasive Problem: No

ID#: 292548

#### **0x11C MLE offloading multiple correctable PCIe events**

- 1. **Problem Description:** Rather than offload multiple correctable error events one at a time, this change will offload and clear all correctable error status registers in a single operation.
- 2. Potential Impact of Problem: Warmstart
- 3. Problem Severity: Service

4. Pervasive Problem: No.

ID#: 293023

#### CDA suspend when updating p6 firmware

- 1. Problem Description: Latent HMC-to-CEC communication problem caused CDA to
- 2. Potential Impact of Problem: Extended CDA service window
- 3. Problem Severity: Service 4. Pervasive Problem: No

## **HMC** hang during repair

**1. Problem Description:** In dual HMC configurations, if the HMC object for one HMC is lost or deleted, the partner HMC can enter a retry loop

2. Potential Impact of Problem: Unable to access the 'good' HMC

Problem Severity: Service
 Pervasive Problem: No

ID#: 293710

### **Incomplete secure erase of self-encrypting drives**

- 1. **Problem Description:** Areas of self-encrypting drives that are reserved for metadata and adapter dumps are not being overwritten during secure erase.
- 2. Potential Impact of Problem: Incomplete erase, and false drive failures
- 3. Problem Severity: Service4. Pervasive Problem: No

ID#: 294675

## Device harvest on large systems causes extended code update time

- 1. **Problem Description:** During code update, there are normally errors generated that are expected, but must still be handled. On large systems, the handling of these errors consumes resources needed to complete the code update process.
- 2. Potential Impact of Problem: Extended concurrent update window
- Problem Severity: Service
  Pervasive Problem: Yes

ID#: 294751

#### **Drive failures during Secure Data Overwrite**

- 1. **Problem Description:** Drive failures during SDO cause early termination, and multiple attempts to complete the process.
- 2. Potential Impact of Problem: Extended SDO runtime
- 3. Problem Severity: Service4. Pervasive Problem: No

ID#: 295522

## Improvements: Improvement for better usability

#### Eliminate Apache Struts v1 vulnerability

- 1. **Problem Description:** Change implements a new servlet class (ParamFilter) that will filter out injected parameters that can otherwise be used to exploit the vulnerability.
- Potential Impact of Problem: none
  Problem Severity: Improvement
- 4. Pervasive Problem: No

#### **Trademarks**

The following terms are trademarks of the International Business Machines Corporation in the United States, other countries, or both.

- > AIX
- > Enterprise Storage Server
- > ESCON
- > FICON
- > i5/OS
- > iSeries
- > IBM
- > pSeries
- > S/390
- > System Storage
- > TotalStorage
- > z/OS
- > zSeries

IBM, the IBM logo, and ibm.com are trademarks or registered trademarks of International Business Machines Corp., registered in many jurisdictions worldwide. Other product and service names might be trademarks of IBM or other companies. A current list of IBM trademarks is available on the web at Copyright and trademark information at http://www.ibm.com/legal/us/en/copytrade.shtml. Adobe, the Adobe logo, PostScript, and the PostScript logo are either registered trademarks or trademarks of Adobe Systems Incorporated in the United States, and/or other countries.

Java and all Java-based trademarks and logos are trademarks or registered trademarks of Oracle and/or its affiliates.

Linux is a trademark of Linus Torvalds in the United States, other countries, or both.

Microsoft, Windows, and Windows NT are trademarks of Microsoft Corporation in the United States, other countries, or both.

© Copyright IBM Corp. 2004, 2011

## **Notices**

This information was developed for products and services offered in the U.S.A. IBM may not offer the products, services, or features discussed in this document in other countries. Consult your local IBM representative for information on the products and services currently available in your area. Any reference to an IBM product, program, or service is not intended to state or imply that only that IBM product, program, or service may be used. Any functionally equivalent product, program, or service that does not infringe any IBM intellectual property right may be used instead. However, it is the user's responsibility to evaluate and verify the operation of any non-IBM product, program, or service.

IBM may have patents or pending patent applications covering subject matter described in this document. The furnishing of this document does not give you any license to these patents. You can send license inquiries, in writing, to:

IBM Director of Licensing IBM Corporation North Castle Drive

Armonk, NY 10504-1785

U.S.A.

The following paragraph does not apply to the United Kingdom or any other country where such provisions are inconsistent with local law:

INTERNATIONAL BUSINESS MACHINES CORPORATION PROVIDES THIS PUBLICATIONS "AS IS" WITHOUT WARRANTY OF ANY KIND, EITHER EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. Some states do not allow disclaimer of express or implied warranties in certain transactions, therefore, this statement may not apply to you.

This information could include technical inaccuracies or typographical errors. Changes are periodically made to the information herein; these changes will be incorporated in new editions of the publication. IBM may make improvements and/or changes in the product(s) and/or the program(s) described in this publication at any time without notice.