

IBM TotalStorage® DS8700 Disk Storage Microcode Bundle 75.15.67.0 Release Note Information

1

Date: March 29, 2011

VRMF Level Data Results:

| | |
|------------------|------------|
| VRMF level From: | 75.15.59.0 |
| VRMF Level To: | 75.15.67.0 |
| Report for: | All DS8700 |

Code Bundle Contents

This table includes code component reference information.

| DS8700 Code Bundle Level | SEA or LMC Version: Used with <i>dscli ver</i> command. | CLI Client Level | Storage Manager Code Level | STAT Tool Level |
|--------------------------|---|------------------|----------------------------|-----------------|
| 75.15.67.0 | 6.5.15.90 | 6.5.15.90 | 5.5.15.1084 | 6.5.15.90 |

Overview of new features and functions supported by Microcode Release:

None

This is a new microcode release only supports the DS8700.

Select Modifications Included in this Release Note:

This is a list of some modifications contained across one or more LIC (License Internal Code) or microcode release(s). The potential impact is variable. Specific environments may aggravate or degrade the potential impact.

Problem(s) reported in this release note may not be in higher levels of code bundles.

Definition of Problem Severity:

1. Acute - An irrecoverable error with potential loss of data.
2. Serious - An irrecoverable error with potential loss of access to data.
3. Moderate - A function not operational and/or performance might be degraded.
4. Service - A recoverable error (no impact) and service improvements.
5. Improvements - Improvement changes for better Usability and Serviceability.

IBM TotalStorage® DS8700 Disk Storage

Microcode Bundle 75.15.67.0 Release Note Information

2

Acute: An irrecoverable error with potential loss of data.

Fence host adapter for SMP mail error

- 1. Problem Description:** Mark host adapter as fenced when SMP mail error is detected when in single cluster mode.
 - 2. Potential Impact of Problem:** Data loss
 - 3. Frequency of Problem:** Low
- ID#: 254572

Serious: An irrecoverable error with potential loss of access to data.

Host commands to undefined LUN ID causes loss of access

- 1. Problem Description:** When a host issues a command to a LUN that is not defined to the control unit a microcode error will result in a dual cluster reboot.
 - 2. Potential Impact of Problem:** Loss of access
 - 3. Frequency of Problem:** Low
- ID#: 252147

Fence RPC card when loss of power master is detected

- 1. Problem Description:** When loss of power master due to communication error is detected the RPC card will be fenced during cluster failover.
 - 2. Potential Impact of Problem:** Loss of access
 - 3. Frequency of Problem:** Low
- ID#: 253407

Moderate: A system path is not operational and performance might be degraded.

Metro Mirror freeze when FlashCopy issues to Global Mirror primary

- 1. Problem Description:** Metro Mirror freeze occurs when FlashCopy to Global Mirror primary devices. When the FlashCopy is copy complete and host issues PRSD 46 to terminate the relationship a microcode error causes a freeze of the Metro Mirror.
 - 2. Potential Impact of Problem:** Metro Mirror freeze
 - 3. Frequency of Problem:** Low
- ID#: 252355

Concurrent Copy fails with 0F-44 sense

- 1. Problem Description:** When a device is part of a suspended XRC session a concurrent copy job will fail with F0-44 sense, indicating the device already belongs to the maximum number of sessions due to a microcode error
 - 2. Potential Impact of Problem:** Concurrent copy jobs fail
 - 3. Frequency of Problem:** Low
- ID#: 247267

IBM TotalStorage® DS8700 Disk Storage

Microcode Bundle 75.15.67.0 Release Note Information

3

Service: A recoverable error, Service improvements.

PPRC sync task encounters track that is "Write in Progress"

- 1. Problem Description:** In GM a PPRC sync task encounters a track that has status of Write in Progress and a microcode error causes a warmstart.
- 2. Potential Impact of Problem:** Warmstart, no suspend
- 3. Frequency of Problem:** High

ID#: 250065

Improvements: Improvement for better usability

NONE

Trademarks and Notices

IBM, ESCON, AIX, FlashCopy, NUMA-Q, DYNIX/PTX, RS/6000, S/390 and AS/400 are registered trademarks and FICON, IBM TotalStorage and Enterprise Storage Server are trademarks of the IBM Corporation. Microsoft, Windows, Windows NT, Windows 2000 and the Windows logo are trademarks or registered trademarks of Microsoft Corporation in the United States, other countries, or both. Intel is a registered trademark of Intel. UNIX is a registered trademark of The Open Group in the United States and other countries. Compaq and Tru64 UNIX are trademarks of Compaq Computer Corporation in the United States and other countries. Sun, Sun Microsystems and Solaris are trademarks or registered trademarks of Sun Microsystems, Inc. in the United States and other countries. Novell is a registered trademark of Novell, Inc. in the United States and other countries. Other company, product, and service names may be trademarks or service marks of others.

Disclaimer

THIS DOCUMENT IS PROVIDED "AS IS" WITHOUT WARRANTY OF ANY KIND. IBM DISCLAIMS ALL WARRANTIES, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION, THE IMPLIED WARRANTIES OF FITNESS FOR A PARTICULAR PURPOSE AND MERCHANTABILITY WITH RESPECT TO THE INFORMATION IN THIS DOCUMENT. BY FURNISHING THIS DOCUMENT, IBM GRANTS NO LICENSES TO ANY PATENTS OR COPYRIGHTS.

Note to Government Users

Documentation related to restricted rights -- Use, duplication or disclosure is subject to restrictions set forth in GSA ADP Schedule Contract with IBM Corporation.