

IBM TotalStorage® DS8700 Disk Storage Microcode Bundle 76.10.144.0 Release Note Information

1

Date: February 17, 2012

VRMF Level Data Results:

VRMF level From:	76.10.141.0
VRMF Level To:	76.10.144.0
Report for:	All DS8700

Code Bundle Contents

This table includes code component reference information.

DS800 Code Bundle Level	SEA or LMC Version: Used with dscli ver command.	CLI Client Level	Storage Manager Code Level
76.10.144.0	6.6.10.500	6.6.10.500	5.6.1.1520

This is a new microcode release only supports the DS8700.

Select Modifications Included in this Release Note:

This is a list of some modifications contained across one or more LIC (License Internal Code) or microcode release(s). The potential impact is variable. Specific environments may aggravate or degrade the potential impact.

Problem(s) fixed and reported in this release note may not be in higher levels of code bundles.

Definition of Problem Severity:

1. Acute - An irrecoverable error with potential loss of data.
2. Serious - An irrecoverable error with potential loss of access to data.
3. Moderate - A function not operational and/or performance might be degraded.
4. Service - A recoverable error (no impact) and service improvements.
5. Improvements - Improvement changes for better Usability and Serviceability.

IBM TotalStorage® DS8700 Disk Storage

Microcode Bundle 76.10.144.0 Release Note Information

2

Acute: An irrecoverable error with potential loss of data.

Warmstart Re-init during CKD Sort Jobs causing data error

- 1. Problem Description:** If there is a warmstart re-init during a sort job in a CKD environment the cache fast write ID does not increment. The host application is not aware of the possible loss of the cache fast write data and does not restart the job. The data may be corrupted and the host application gets down level data for the sort job.
- 2. Potential Impact of Problem:** loss of data
- 3. Problem Severity:** High Impact
- 4. Pervasive Problem:** No

ID#: 260801

Serious: An irrecoverable error with potential loss of access to data.

Hosts with new WWPNs unable to re-login

- 1. Problem Description:** When multiple hosts have new WWPNs some ports will be stuck in a busy state due to a microcode error. This problem might be encountered after re-cabling host to control unit connections.
- 2. Potential Impact of Problem:** loss of access
- 3. Problem Severity:** HIPER
- 4. Pervasive Problem:** Yes

ID#: 262822

During CCL IML of the second cluster on previous code level

- 1. Problem Description:** During CCL if a failure occurs after the first cluster has completed the code update and the second cluster is allowed IML back on the lower code level after repair loss of access will occur.
- 2. Potential Impact of Problem:** loss of access
- 3. Problem Severity:** High Impact
- 4. Pervasive Problem:** No

ID#: 261727

Microcode logic error results in dual cluster reboot

- 1. Problem Description:** During cluster IML Back the available DA sends global metadata to the partner DA. If an error is detected in the metadata then error recovery incorrectly reboots both clusters.
- 2. Potential Impact of Problem:** loss of access
- 3. Problem Severity:** High Impact
- 4. Pervasive Problem:** No

ID#: 261787

IBM TotalStorage® DS8700 Disk Storage

Microcode Bundle 76.10.144.0 Release Note Information

3

Moderate: A system path is not operational and performance might be degraded.

GM hang condition due to a microcode error

- 1. Problem Description:** Global Mirror hang results from a microcode error. Sometimes the microcode error is detected and warmstart recovers the error and sometimes the error is not detected by microcode and warmstart must be forced to recover the error
- 2. Potential Impact of Problem:** Global Mirror hang
- 3. Problem Severity:** Moderate
- 4. Pervasive Problem:** Yes

ID#: 262177

Service: A recoverable error, Service improvements.

CEC op panel displays B1811404 for recovered error

- 1. Problem Description:** After a temporary CEC to RPC communication failure the CEC op panel will display B1811404 due to a microcode error
- 2. Potential Impact of Problem:** Unneeded RPC replacement
- 3. Problem Severity:** Service
- 4. Pervasive Problem:** No

ID#: 259445

DSCLI lsavailpprcpath command returns CMUC00234I error

- 1. Problem Description:** Command reject prevents all valid PPRC paths from being displayed by the lsavailpprcpath command. This problem is due to a microcode error.
- 2. Potential Impact of Problem:** Invalid PPRC path information
- 3. Problem Severity:** Service
- 4. Pervasive Problem:** No

ID#: 265457

DSGUI menus not accessible with Mozilla Firefox® 3.5

- 1. Problem Description:** DSGUI main page will load but when a menu is selected it will not complete loading.
- 2. Potential Impact of Problem:** No DSGUI access from browser
- 3. Problem Severity:** Service
- 4. Pervasive Problem:** No

ID#: 264541

Improvements: Improvement for better usability

NONE

IBM TotalStorage® DS8700 Disk Storage

Microcode Bundle 76.10.144.0 Release Note Information

Trademarks

The following terms are trademarks of the International Business Machines Corporation in the United States, other countries, or both.

- > AIX
- > Enterprise Storage Server
- > ESCON
- > FICON
- > i5/OS
- > iSeries
- > IBM
- > pSeries
- > S/390
- > System Storage
- > TotalStorage
- > z/OS
- > zSeries

IBM, the IBM logo, and [ibm.com](http://www.ibm.com) are trademarks or registered trademarks of International Business Machines Corp., registered in many jurisdictions worldwide. Other product and service names might be trademarks of IBM or other companies. A current list of IBM trademarks is available on the web at Copyright and trademark information at <http://www.ibm.com/legal/us/en/copytrade.shtml>.

Adobe, the Adobe logo, PostScript, and the PostScript logo are either registered trademarks or trademarks of Adobe Systems Incorporated in the United States, and/or other countries. Java and all Java-based trademarks and logos are trademarks or registered trademarks of Oracle and/or its affiliates.

Linux is a trademark of Linus Torvalds in the United States, other countries, or both. Mozilla Firefox is a trademark of Mozilla Corporation.

Microsoft, Windows, and Windows NT are trademarks of Microsoft Corporation in the United States, other countries, or both.

© Copyright IBM Corp. 2004, 2011

Notices

This information was developed for products and services offered in the U.S.A. IBM may not offer the products, services, or features discussed in this document in other countries. Consult your local IBM representative for information on the products and services currently available in your area. Any reference to an IBM product, program, or service is not intended to state or imply that only that IBM product, program, or service may be used. Any functionally equivalent product, program, or service that does not infringe any IBM intellectual property right may be used instead. However, it is the user's responsibility to evaluate and verify the operation of any non-IBM product, program, or service.

IBM may have patents or pending patent applications covering subject matter described in this document. The furnishing of this document does not give you any license to these patents. You can send license inquiries, in writing, to:

IBM Director of Licensing
IBM Corporation
North Castle Drive
Armonk, NY 10504-1785
U.S.A.

IBM TotalStorage® DS8700 Disk Storage

Microcode Bundle 76.10.144.0 Release Note Information

5

The following paragraph does not apply to the United Kingdom or any other country where such provisions are inconsistent with local law:

INTERNATIONAL BUSINESS MACHINES CORPORATION PROVIDES THIS PUBLICATIONS "AS IS" WITHOUT WARRANTY OF ANY KIND, EITHER EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. Some states do not allow disclaimer of express or implied warranties in certain transactions, therefore, this statement may not apply to you.

This information could include technical inaccuracies or typographical errors. Changes are periodically made to the information herein; these changes will be incorporated in new editions of the publication. IBM may make improvements and/or changes in the product(s) and/or the program(s) described in this publication at any time without notice.