Tivoli. software

IBM

Work Order Pick

WO: 1002 **Rebuild Feedwater Pump**

Site: BEDFORD **Storeroom: CENTRAL**

Item: 11453: Seal, Mechanical, Self Aligning- 1 In ID
Qty: 1

Bin	Lot	Condition Code	Current Balance	Issue Unit
A-4-9	A-431		20	
A-4-9	ABC		1	
G-5-3	A-431		1	

Item: 117084: Shaft- 1 Inch Dia
Qty: 1

Bin	Lot	Condition Code	Current Balance	Issue Unit
C-6-2			6	

Item: 12853: Impeller- 4-1/2 Inch Dia
Qty: 1

Bin	Lot	Condition Code	Current Balance	Issue Unit
B-5-2			6	

Item: 20778: Housing- Centrifugal Pump
Qty: 1

Bin	Lot	Condition Code	Current Balance	Issue Unit
B-5-8			1	

Item: XMP-9500: Gasket- AR46
Qty: 1

Bin	Lot	Condition Code	Current Balance	Issue Unit
D-9-5			12	