Asset Measurement History

Site: BEDFORD
Type:

Asset: 11430
Location: BR430
Description: Condensate Return Pump- Centrifugal/100GPM/60FTHD

Tivoli. software

IBM®

Asset Measurement History

Point: 1001
Description: Outlet Pressure Monitor
Meter Name: O-PRESSUR
Meter Description: Outlet Pressure
Meter Type: GAUGE
Measure Unit: PSI

Warning Lower Limit: 3500
Warning Upper Limit: 5000
Action Lower Limit: 3200
Action Upper Limit: 5500

Measurement Date	Measurement Value	Results	Inspector
2/9/05 7:55:00 AM	4473		WILSON
2/2/05 7:55:00 AM	4482		WILSON
1/26/05 7:55:00 AM	4478		WILSON
1/19/05 7:54:00 AM	4476		WILSON
1/12/05 7:54:00 AM	4409		WILSON
1/5/05 7:53:00 AM	3397	WARNING	WILSON
12/30/04 7:53:00 AM	4402		WILSON
12/23/04 7:52:00 AM	4398		WILSON
12/16/04 7:51:00 AM	4395		WILSON
12/9/04 7:51:00 AM	4390		WILSON
12/2/04 7:49:00 AM	4267		WILSON

Asset Measurement History

Site: BEDFORD
Type:

Asset: 11450
Location: BR450
Description: Feed Water Pump- Centrifugal/100GPM/60FTHD

Tivoli. software

IBM®

Asset Measurement History

Point: 1002
Description: Outlet Pressure Monitor
Meter Name: O-PRESSUR
Meter Description: Outlet Pressure
Meter Type: GAUGE
Measure Unit: PSI

Warning Lower Limit: 3500
Warning Upper Limit: 5000
Action Lower Limit: 3200
Action Upper Limit: 5500

Measurement Date	Measurement Value	Results	Inspector
2/9/05 7:55:00 AM	4473		WILSON
2/2/05 7:55:00 AM	4482		WILSON
1/26/05 7:55:00 AM	4478		WILSON
1/19/05 7:54:00 AM	4476		WILSON
1/12/05 7:54:00 AM	4409		WILSON
1/5/05 7:53:00 AM	3397	WARNING	WILSON
12/30/04 7:53:00 AM	4402		WILSON
12/23/04 7:52:00 AM	4398		WILSON
12/16/04 7:51:00 AM	4395		WILSON
12/9/04 7:51:00 AM	4390		WILSON
12/2/04 7:49:00 AM	4267		WILSON