Tivoli. software

IBM®

Work Order List

Site: BEDFORD

Work Order	Description	Type	Status	Priority	Lead	Location:	Asset	Job Plan	Parent WO	Schedule Start	Schedule Finish
1000	Relocate Guard Rails Around Compressor	CM	WAPPR	2		BR300	11300			3/15/11	3/16/11
1002	Rebuild Feedwater Pump	CM	APPR	9		BR450	11450	JP11430			
1004	Generator Overhaul	CM	INPRG	1		BR230	11230	JP11210			
1006	Feedwater Pump Service	CM	APPR	7		BR450	11450	JP11430			
1008	Repair Damaged Conduit Feeding Generator	CM	WAPPR	7		BR230	11230				
1018	Paint Guard Rail Around #1 Fan	CM	WAPPR	4		BR210	11210				
1020	Generator Overhaul	EM	WSCH	2		BR230	11230	JP11210		4/22/02	4/28/02
1024	Condensate Return Pump Quarterly Service	PM	WSCH	9		BR430	11430	JP11430A			
1026	HVAC Quarterly Inspections & Certification	PM	WSCH	9		BR200	11200	INS11200			
1027	Compressor Quarterly Inspection and Certification	PM	WSCH	9		BR300	11300	INS11300			
1028	Burner Quarterly Inspection and Certification	PM	WSCH	9		BR460	11460	INS11460			
1144	Investigate Low/High Outlet Pressure		COMP	2		BR450	11450	JPOUTPR			
1176	parent		WAPPR			BR400	11400				
3001	HVAC Quarterly Inspections & Certification	PM	WSCH	9		BR200	11200	INS11200			
3002	Compressor Quarterly Inspection and Certification	PM	WSCH	9		BR300	11300	INS11300			
3003	Burner Quarterly Inspection and Certification	PM	WSCH	9		BR460	11460	INS11460			
31150	11430 prob work	CM	APPR	2		BR430	11430			11/24/01	11/25/01
31250	11200 prob work	CM	APPR	2		BR200	11200			11/26/01	11/27/01
31755	11300 prob work-see miller	CM	APPR	2		BR300	11300	JP3004		12/17/01	12/18/01
40060	Inspection	PM	APPR	4		BR431	23972			6/24/00	6/29/00
40092	ROUTINE MAINTENANCE	PM	APPR	2		BR460	11460			10/7/00	10/12/00
40093	MAINTENANCE	PM	APPR	3		BR430	11430	JP11430A		10/3/00	10/7/00
40101	ROUTINE MAINTENANCE	PM	APPR	3		BR460	11460			11/6/00	11/11/00
40111	ROUTINE MAINTENANCE	PM	APPR	3		BR460	11460			12/6/00	12/11/00
40112	MAINTENANCE	PM	APPR	3		BR430	11430	JP11430A		12/2/00	12/6/00
40121	Inspection and Certification	PM	APPR	3		BR430	11430	JP11430A		12/31/00	1/5/01
40122	Inspection	PM	APPR	2		BR400	11400			12/6/00	12/11/00
40123	Inspection and Certification	PM	APPR	3		BR460	11460			1/5/01	1/10/01
40124	ROUTINE MAINTENANCE	PM	APPR	3		BR460	11460			1/5/01	1/10/01
41011	Inspection	PM	APPR	4		BR431	23972			2/4/01	2/9/01
41012	ROUTINE MAINTENANCE	PM	APPR	3		BR460	11460			2/4/01	2/9/01
41013	R&R	PM	APPR	3		BR430	11430	JP11430A		2/4/01	2/9/01
41021	Inspection and Certification	PM	APPR	3		BR430	11430	JP11430A		4/5/01	4/10/01

Work Order List

Site: BEDFORD

Work Order	Description	Type	Status	Priority	Lead	Location:	Asset	Job Plan	Parent WO	Schedule Start	Schedule Finish
41023	ROUTINE MAINTENANCE	PM	APPR	2		BR460	11460			3/11/01	3/16/01
41031	ROUTINE MAINTENANCE	PM	APPR	3		BR460	11460			4/10/01	4/15/01
41032	R&R	PM	APPR	3		BR430	11430	JP11430A		3/29/01	4/3/01
41041	Inspection and Certification	PM	APPR	2		BR400	11400			5/5/01	5/10/01
41042	ROUTINE MAINTENANCE	PM	APPR	3		BR460	11460			5/10/01	5/15/01
41051	ROUTINE MAINTENANCE	PM	APPR	3		BR460	11460			6/6/01	6/10/01
41052	R&R	PM	APPR	3		BR430	11430	JP11430A		5/28/01	6/2/01
41061	Inspection	PM	APPR	2		BR300	11340	JP1314A		7/4/01	7/9/01
41062	Inspection	PM	APPR	4		BR431	23972			7/4/01	7/9/01
41064	ROUTINE MAINTENANCE	PM	APPR	3		BR460	11460			6/29/01	7/4/01
41071	Inspection	PM	APPR	2		BR300	11340	JP1314A		8/3/01	8/8/01
41073	R&R	PM	APPR	3		BR430	11430	JP11430A		7/29/01	8/3/01
41081	Inspection	PM	APPR	2		BR400	11400			8/28/01	9/2/01
41082	ROUTINE MAINTENANCE	PM	APPR	2		BR460	11460			9/2/01	9/7/01
41091	R&R	PM	APPR	3		BR430	11430	JP11430A		10/12/01	10/16/01
42001	Inspection and Certification	PM	APPR	3		BR430	11430	JP11430A		10/27/01	10/28/01
42002	Inspection and Certification	PM	APPR	2		BR400	11400			11/6/01	11/7/01

Tivoli. software

IBM®

Work Order List

Site: BEDFORD

Work Order	Description	Type	Status	Priority	Lead	Location:	Asset	Job Plan	Parent WO	Schedule Start	Schedule Finish
42003	Inspection	PM	APPR	4		BR431	23972			10/12/01	10/16/01
42005	Inspection	PM	APPR	4		BR431	23972			1/20/02	1/22/02
42006	Inspection	PM	APPR	4		BR460	11460			9/10/01	9/12/01
42007	Inspection	PM	APPR	4		BR460	11460			12/13/01	12/11/01
43001	11340 PM	PM	APPR	2		BR300	11340	JP1314A		1/11/02	1/12/02
43002	11300 PM	PM	APPR	2		BR300	11300			1/11/02	1/12/02
43003	11340 PM	PM	APPR	2		BR300	11340	JP1314A		3/12/02	3/13/02
43004	11300 PM	PM	APPR	2		BR300	11300			3/12/02	3/13/02
43005	11340 PM WORK	PM	APPR	2		BR300	11340	JP1314A		5/11/02	5/12/02
43006	11300 PM work	PM	APPR	2		BR300	11300			5/11/02	5/12/02
43007	11340 PM	PM	APPR	2		BR300	11340	JP1314A		7/10/02	7/11/02
43008	11300 PM WORK	PM	APPR	2		BR300	11300			7/10/02	7/11/02
43009	11340 PM work	PM	APPR	2		BR300	11340	JP1314A		9/8/02	9/9/02
43010	11300 PM	PM	APPR	2		BR300	11300			9/8/02	9/9/02
43011	11400 PM WORK	PM	APPR	2		BR400	11400			1/11/02	1/12/02
43012	11400 PM work	PM	APPR	2		BR400	11400			3/12/02	3/13/02
43013	11400 PM work	PM	APPR	2		BR400	11400			5/11/02	5/12/02
43014	11400 PM WORK	PM	APPR	2		BR400	11400			7/10/02	7/11/02
43015	11400 PM work	PM	APPR	2		BR400	11400			9/8/02	9/9/02
43016	11460 PM work	PM	APPR	3		BR460	11460			12/27/01	12/28/01
43017	11460 PM WORK	PM	APPR	3		BR460	11460			2/25/02	2/26/02
43018	11460 PM work	PM	APPR	3		BR460	11460			4/26/02	4/27/02
43019	11460 PM tasks	PM	APPR	3		BR460	11460			6/25/02	6/26/02
43020	11460 PM WORK	PM	APPR	3		BR460	11460			8/24/02	8/25/02
43041	11430 PM WORK	PM	APPR	3		BR430	11430	JP11430A		1/1/02	1/2/02
43042	11430 PM work jobs	PM	APPR	3		BR430	11430	JP11430A		3/2/02	3/3/02
43043	11430 PM tasks	PM	APPR	3		BR430	11430	JP11430A		5/1/02	5/2/02
43044	11430 PM WORK	PM	APPR	3		BR430	11430	JP11430A		6/30/02	7/1/02
43045	11430 PM work jobs	PM	APPR	3		BR430	11430	JP11430A		8/29/02	8/30/02
43046	11430 PM tasks	PM	APPR	3		BR430	11430	JP11430A		10/28/02	10/29/02
43047	23972 PM WORK	PM	APPR	4		BR431	23972			1/26/02	1/27/02
43048	23972 PM work jobs	PM	APPR	4		BR431	23972			3/17/02	3/18/02
43049	23972 PM tasks	PM	APPR	4		BR431	23972			5/6/02	5/7/02

Work Order List

Site: BEDFORD

Work Order	Description	Type	Status	Priority	Lead	Location:	Asset	Job Plan	Parent WO	Schedule Start	Schedule Finish
43050	23972 PM WORK	PM	APPR	4		BR431	23972			6/25/02	6/26/02
43051	23972 PM work jobs	PM	APPR	4		BR431	23972			8/14/02	8/15/02
43052	23972 PM tasks	PM	APPR	4		BR431	23972			10/3/02	10/4/02
43053	23972 PM WORK	PM	APPR	4		BR431	23972			11/22/02	11/23/02
43054	23972 PM WORK	PM	APPR	4		BR431	23972			1/11/03	1/12/03
43055	23972 PM tasks	PM	APPR	4		BR431	23972			3/2/03	3/3/03
43070	11200 PM WORK	PM	APPR	2		BR200	11200			1/26/02	1/27/02
43071	11200 PM tasks	PM	APPR	2		BR200	11200			3/17/02	3/18/02
43072	11200 pm tasks	PM	APPR	2		BR200	11200			5/6/02	5/7/02
43073	11200 PM WORK	PM	APPR	2		BR200	11200			6/25/02	6/26/02
43074	11200 PM tasks	PM	APPR	2		BR200	11200			8/14/02	8/15/02
43075	11200 pm tasks	PM	APPR	2		BR200	11200			10/3/02	10/4/02
43076	11200 PM WORK	PM	APPR	2		BR200	11200			11/22/02	11/23/02
43077	11250 PM tasks	PM	APPR	2		BR200	11250			1/26/02	1/27/02
43078	11250 pm tasks	PM	APPR	2		BR200	11250			3/17/02	3/18/02
43079	11250 work - pm	PM	APPR	2		BR200	11250			5/6/02	5/7/02
43080	11250 PM tasks	PM	APPR	2		BR200	11250			6/25/02	6/26/02

Work Order List

Site: BEDFORD

Work Order	Description	Type	Status	Priority	Lead	Location:	Asset	Job Plan	Parent WO	Schedule Start	Schedule Finish
43081	11250 pm tasks	PM	APPR	2		BR200	11250			8/14/02	8/15/02
43082	11250 work - pm	PM	APPR	2		BR200	11250			10/3/02	10/4/02
43083	11250 PM tasks	PM	APPR	2		BR200	11250			11/22/02	11/23/02
43084	11250 pm tasks	PM	APPR	2		BR200	11250			1/11/03	1/12/03
5011	HVAC Quarterly Inspections & Certification	PM	WAPPR	3		BR200	11200	INS11200			
5012	Compressor Quarterly Inspection and Certification	PM	WAPPR	4		BR300	11300	INS11300			
5013	Burner Quarterly Inspection and Certification	PM	WAPPR	4		BR460	11460	INS11460			
51011	PM Work - 11430	PM	APPR	4		BR430	11430	JP11430A		3/27/02	3/30/02
51012	PM Work - 11430	PM	APPR	4		BR430	11430	JP11430A		5/26/02	5/29/02
51013	PM Work - 11430	PM	APPR	4		BR430	11430	JP11430A		7/5/02	7/28/02
51014	PM Work - 11430	PM	APPR	4		BR430	11430	JP11430A		9/23/02	9/26/02
51015	PM Work - 11430	PM	APPR	4		BR430	11430	JP11430A		11/22/02	11/25/02
51016	PM Work - 11430	PM	APPR	4		BR430	11430	JP11430A		1/21/03	1/24/03
51017	PM Work - 11430	PM	APPR	4		BR430	11430	JP11430A		3/22/03	3/25/03
51018	PM Work - 11430	PM	APPR	4		BR430	11430	JP11430A		3/22/03	3/25/03
6011	HVAC Quarterly Inspections & Certification	PM	WAPPR	2		BR200	11200	INS11200		1/19/02	1/24/02
6012	Compressor Quarterly Inspection and Certification	PM	WAPPR	2		BR300	11300	INS11300		2/8/02	2/14/02
6013	Burner Quarterly Inspection and Certification	PM	WAPPR	2		BR460	11460	INS11460		2/8/02	2/14/02
7331	Engineering and layout drawings	CP	WAPPR	9		BR300	11300		7330	3/28/99	3/29/99
91091	11450 BREAKDOWN	EM	APPR	1		BR450	11450			10/12/01	10/13/01

Number of Records: 120