Tivoli. software

IBM

Routes Analysis

Route: 1002 **Inspect Fire Extinguishers** **Site: BEDFORD**

Sequence	Asset	Description	Location	Description	Job Plan	Description	Route Stop Description
10	1001	Fire Extinguisher					
20	1002	Fire Extinguisher					
30	1003	Fire Extinguisher					
40	1004	Fire Extinguisher					
50	1005	Fire Extinguisher					
60	1006	Fire Extinguisher					
70	1007	Fire Extinguisher					

Route: 1005 **Inspect PC Workstations** **Site: BEDFORD**

Sequence	Asset	Description	Location	Description	Job Plan	Description	Route Stop Description
10	PC1001	DataStar Desk Wizard PC			INS-PC	PC Inspection	
20	PC1002	DataStar Desk Wizard PC			INS-PC	PC Inspection	

Route: Q-PUMPS **Quarterly Pump Service** **Site: BEDFORD**

Sequence	Asset	Description	Location	Description	Job Plan	Description	Route Stop Description
	11470	Centrifugal Pump 100 GPM, 60 FT-HD					
	11430	Centrifugal Pump 100GPM/ 60FT HD					
	11450	Centrifugal Pump 100GPM/ 60FTHD					

Route: I-95N SI **I-95N in 10 mile segment increments (SI)** **Site: BEDFORD**

Sequence	Asset	Description	Location	Description	Job Plan	Description	Route Stop Description
	I-95N	Interstate 95 Northbound					