Drilldown of Asset Failures

Problem Code: LEAK
Description: Leaking
Asset: 11430
Description: Centrifugal Pump 100GPM/60FT HD
Location: BR430
Description: Condensate Return Pump- Centrifugal/100GPM/60FTHD
Site: BEDFORD

Start Date: 1/1/95
End Date: 1/1/05
Asset Moved: N

Tivoli. software

IBM

Drilldown of Asset Failures

Problem Code: LEAK
Description: Leaking
Asset: 11430
Description: Centrifugal Pump 100GPM/60FT HD
Location: BR430
Description: Condensate Return Pump- Centrifugal/100GPM/60FTHD
Site: BEDFORD

Start Date: 1/1/95
End Date: 1/1/05
Asset Moved: N

Fail Date		WO	Cause	Description	Remedy	Description	Downtime During Failures (Hrs)
9/26/01	8:35:00 PM	1488	SEAL	Seal Leaking	REPLSEAL	Replace Seal	2.50
4/12/01	8:37:00 PM	1638	SEAL	Seal Leaking	ADJSEAL	Adjust Seal	0.50
2/21/01	8:04:00 PM	1277	SEAL	Seal Leaking	REPLSEAL	Replace Seal	3.00
1/5/01	9:18:00 PM	3838	SEAL	Seal Leaking	REPLSEAL	Replace Seal	3.50
7/2/00	9:07:00 PM	3038	SEAL	Seal Leaking	REPLSEAL	Replace Seal	2.50
6/30/00	9:30:00 PM	5256	SEAL	Seal Leaking	REPLSEAL	Replace Seal	3.00
11/3/99	8:44:00 PM	2362	SEAL	Seal Leaking	REPLSEAL	Replace Seal	3.00
3/10/99	9:47:00 PM	6727	SEAL	Seal Leaking	REPLSEAL	Replace Seal	3.00
7/24/98	8:40:00 PM	1695	SEAL	Seal Leaking	REPLSEAL	Replace Seal	3.50
7/31/96	10:05:00 PM	7721	SEAL	Seal Leaking	REPLSEAL	Replace Seal	2.50

Total Downtime During Failures(Hrs): 27.00